CONSTRUCTION EQUIPMENT SPM539972 EXPORT MUSTANG MTL 16 21309383 - DIESEL ENG

 Sample No:
 VCP405579

 Oil Type:
 MOBIL MOBIL1 10W30

 Job No:
 SPM539972 EXPORT

VOLVO

SAMPLE II	NFORMATION				
Sample Number		VCP405579			
Sample Date		20 Apr 2023			
Machine Hours		671			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
Visc @ 100°C	cSt	12.2			
Base Number (BN)	mg KOH/g	7.3			
Oxidation (PA)	%	50			
CONTAMINATION					
Soot %	%	■0.1			
	0/				

Soot %	%	0.1	 	
Nitration (PA)	%	54	 	
Sulfation (PA)	%	42	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	15	 	
Sodium	ppm	5	 	
Potassium	ppm	1	 	

WEAR N	METALS			
Iron	ppm	13	 	
Copper	ppm	3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	3	 	
Chromium	ppm	0	 	
Molybdenum	ppm	32	 	
Nickel	ppm	0	 	
Titanium	ppm	1	 	
Silver	ppm	0	 	
Manganese	ppm	□ <1	 	
Vanadium	ppm	<1	 	

variaulu

ADDITIVES					
Calcium	ppm	2272			
Magnesium	ppm	194			
Zinc	ppm	1081			
Phosphorus	ppm	889			
Barium	ppm	0			
Boron	ppm	18			
	1-1-11				



ALTA CONSTRUCTION EQUIPMENT LLC

G-3283 S. DORT HIGHWAY BURTON, MI US 48529 Contact: BURTON SERVICE BURTON.SERVICE@ALTAEQUIPMENT.COM T: E:

Diagnosis

Resample at the next service interval to monitor.Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

 Depot:
 VOLVO5023

 Unique No:
 10454997

 Signed:
 Sean Felton

 Report Date:
 04 May 2023


Contact/Location: BURTON SERVICE - VOLVO5023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO5023 [WUSCAR] 05836194 (Generated: 07/03/2023 10:53:37) Rev: 1

Contact/Location: BURTON SERVICE - VOLVO5023