Sample No: VCP422073
Oil Type: VOLVO WB 102

**Job No:** 553239 STATEWIDE MAT

SAMPLE	INFORMATION	1		
Sample Number	_	VCP422073	VCP314124	 
Sample Date		09 May 2023	24 May 2021	 
Machine Hours		8920	7387	 
Oil Hours		0	0	 
Oil Changed		Not Changd	Not Changd	 
Sample Status		ABNORMAL	NORMAL	 
VOLVO	DITION			
OIL CON	DITION			
Visc @ 40°C	cSt	<b>41.8</b>	<b>43.6</b>	 
VOLVO				
LUNTAN	MINATION			
_		NEC	NEC	
Water	%	NEG	NEG	
Silicon	ppm	<b>13</b>	<b>1</b> 4	 
Sodium	ppm	<b>4</b>	<b>6</b>	 
Potassium	ppm	■0	<b></b> <1	 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>□</b> 24	□23	 
Copper	ppm	<u></u> 334	173	 
Lead	ppm	<b>-&lt;1</b>	<b>1</b>	 
Tin	ppm	<b>1</b>	<1	 
Aluminum	ppm	<b>-</b> <1	2	 
Chromium	ppm	<u> </u>	<1	 
Molybdenum	ppm	<b>2</b>	<b>2</b>	 
Nickel	ppm	<b>2</b>	3	 
Titanium	ppm	0	<1	 
Silver	ppm	0	<1	 
Manganese	ppm	<b>2</b>	<b>1</b>	 
Vanadium	ppm	0	<1	 
ADDITIV	731			
Calcium	ppm	■3758	■3929	 
Magnesium	ppm	<b>24</b>	23	 
Zinc	ppm	<b>1549</b>	<b>1516</b>	 
Phosphorus	ppm	<b>1229</b>	<b>1</b> 320	 
Barium	ppm	■0	<b>0</b>	 
Boron	ppm	<b>123</b>	<b>1</b> 32	 



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
9601 BOGGY CREEK RD
ORLANDO, FL
US 32824
Contact: Robert LaPlante
robert.laplante@altg.com
T: (407)508-9736
F: (407)659-8720

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0096Unique No:10470002Signed:Don BaldridgeReport Date:16 May 2023



## **CONSTRUCTION EQUIPMENT**





