CONSTRUCTION EQUIPMENT SW1019028 PERKINS VOLVO EC550E 310081 - RIGHT SWING DI

 Sample No:
 VCP406910

 Oil Type:
 GEAR OIL SAE 80W90

 Job No:
 SW1019028 PERKINS

TOTATO

SAMPLE	INFORMATION	l		
Sample Number	-	VCP406910	 	
Sample Date		19 May 2023	 	
Machine Hours		560	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>176</b>	 	
CONTAN	MINATION			
Silicon	ppm	<b>1</b> 9	 	
Sodium	ppm	2	 	
Potassium	ppm	2	 	
WEAR N	METALS			
Iron	ppm	101	 	
Copper	ppm	<b>1</b> 32	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	4	 	
Chromium	ppm	3	 	
Molybdenum	ppm	<b></b> <1	 	
Nickel	ppm	<b>  </b> <1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	9	 	
Vanadium	ppm	0	 	
ADDITIN	/ES			
Calcium	ppm	3	 	
Magnesium	ppm	0	 	
Zinc	ppm	83	 	
Phosphorus	ppm	360	 	
<b>-</b> ·				



## ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO6174Unique No:10493999Signed:Jonathan HesterReport Date:01 Jun 2023

■ <1

3

ppm

ppm

Barium

Boron

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO

