

CONSTRUCTION EQUIPMENT HITACHI 65218 - DIESEL ENGINE

 Sample No:
 VCP406275

 Oil Type:
 MOBIL 15W40

Job No:

	INFORMATION			
Sample Number		VCP406275	 	
Sample Date		20 Jun 2023	 	
Machine Hours		3475	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 100°C	cSt	13.5	 	
Base Number (BN		9.7	 	
Oxidation (PA)	%	53	 	
Oxidation (FA)	70	33	 	
VOLVO				
CONTAN	MINATION			
Soot %	%	0.1	 	
Nitration (PA)	%	41	 	
Sulfation (PA)	%	51	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	7	 	
Sodium	ppm	0	 	
Potassium	ppm	1	 	
WEAR N			 	
Iron	nnm	4	 	

Iron ppm 4 Copper ■ <1 ppm Lead **||** <1 ppm Tin 0 ppm Aluminum ppm 0 **||** <1 Chromium ppm Molybdenum 74 ppm Nickel **||** <1 ppm Titanium 0 ppm Silver 0 ppm Manganese **||** <1 ppm Vanadium ppm 0

ADDITIVES 1439 Calcium ppm 1014 Magnesium ppm Zinc 1432 ppm Phosphorus ppm 1245 Barium 0 🔲 ppm 21 Boron ppm





ARNOLD MACHINERY COMPANY

3330 NORTH YELLOWSTONE HIGHWAY IDAHO FALLS, ID US 83401 Contact: JASON MERRILL jmerrill@arnoldmachinery.com T: (208)523-0822 F: (208)523-9918

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

 Depot:
 VOLV00077

 Unique No:
 10533542

 Signed:
 Wes Davis

 Report Date:
 28 Jun 2023


Contact/Location: JASON MERRILL - VOLVO0077

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0077 [WUSCAR] 05883059 (Generated: 08/14/2023 11:06:44) Rev: 1

Contact/Location: JASON MERRILL - VOLVO0077