

Sample No: VCP404210
Oil Type: DEXRON III

**Job No:** SW1016064 LKQ

SAMPLE	E INFORMATION	1		
Sample Number		VCP404210	 	
Sample Date		21 Jun 2023	 	
Machine Hours		6452	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CON	INITION			
Visc @ 40°C	cSt	27.8	 	
VISC @ 40 C	CSL	<u> </u>	 	
VOLVO				
CONTAI	MINATION			
Silicon	ppm	<b>3</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	■3	 	
WEAR N	METALS			
Iron	ppm	■4	 	
Copper	ppm	■1	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>-</b> <1	 	
Nickel	ppm	<b></b>	 	
Titanium	ppm	<1	 	
Silver	ppm	<b>0</b>	 	
Manganese Vanadium	ppm	<b>□</b> <1	 	
variaulum	ppm	U	 	
VOLVO				
ADDITIV	VEZ .			
Calcium	ppm	■94	 	
Magnesium	ppm	<b>7</b>	 	
Zinc	ppm	<b>13</b>	 	
Phosphorus	ppm	<b>179</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>73</b>	 	



## ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO6174Unique No:10535238Signed:Wes DavisReport Date:30 Jun 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

