
Sample No:	VCP425885
Oil Type:	DEXRON III
Job No:	SWO-063459

VOLVO

## SAMPLE INFORMATION VCP425885 Sample Number VCP392782 VCP367339 VCP367024 Sample Date 22 Jun 2023 14 Feb 2023 03 Nov 2022 04 Aug 2022 Machine Hours 6450 5835 5435 4970 Oil Hours 0 0 0 0 Oil Changed Changed Changed Not Changd Not Changd NORMAL NORMAL Sample Status NORMAL NORMAL **OIL CONDITION** Visc @ 40°C cSt 28.4 28.1 28.27 28.1 CONTAMINATION Silicon ppm 3 3 3 1 Sodium **4** 5 2 2 ppm Potassium 2 0 0 0 ppm WEAR METALS Iron ppm 15 17 12 9 Copper ppm 15 13 12 9 Lead ppm 0 🔲 0 0 0 2 Tin ppm 3 2 2



**ADDITIVES** Calcium 80 75 79 68 ppm Magnesium 3 ■<1 **4** 0 ppm Zinc 0 0 0 0 ppm 185 201 180 Phosphorus ppm **192** Barium 0 0 ppm 0 0 Boron ppm 85 100 85 94



## WHITAKER CONTRACTING

692 CONVICT CAMP RD GUNTERSVILLE, AL US 35976 Contact: BROTHER WHITAKER BrotherWhitaker@whitaker-contracting.com T: (256)298-3905 F:

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.


Depot:	WHIGUN
Unique No:	10536456
Signed:	Wes Davis
Report Date:	02 Jul 2023

## **CONSTRUCTION EQUIPMENT**




GRAPHS

VOLVO







Contact/Location: BROTHER WHITAKER - WHIGUN