

CONSTRUCTION EQUIPMENT

SWA275007 HERC VOLVO EC140EL 311491 - RIGHT TRACK DRIV

Sample No: VCP410030

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: SWA275007 HERC

| VOLVO | | | | | |
|--------------------|-------------|-------------|--|--|--|
| SAMPLE INFORMATION | | | | | |
| Sample Number | - | VCP410030 | | | |
| Sample Date | | 27 Jun 2023 | | | |
| Machine Hours | | 2220 | | | |
| Oil Hours | | 0 | | | |
| Oil Changed | | Changed | | | |
| Sample Status | | ABNORMAL | | | |
| | | | | | |
| OIL CONDITION | | | | | |
| Visc @ 40°C | cSt | 142 | | | |
| VOLVO | | | | | |
| CONTAMINATION | | | | | |
| Silicon | ppm | 21 | | | |
| Sodium | ppm | 4 | | | |
| Potassium | ppm | 0 | | | |
| | | | | | |
| WEAR N | AETAI C | | | | |
| _ | | | | | |
| Iron | ppm | 650 | | | |
| Copper | ppm | 1 | | | |
| Lead | ppm | 0 | | | |
| Tin | ppm | <u>▲</u> 57 | | | |
| Aluminum | ppm | 2 | | | |
| Chromium | ppm | 11 | | | |
| Molybdenum | ppm | ■ <1 | | | |
| Nickel | ppm | ■3 | | | |
| Titanium | ppm | <1 | | | |
| Silver | ppm | 0 | | | |
| Manganese | ppm | ■ 11 0 | | | |
| Vanadium | ppm | U | | | |
| VOLVO | | | | | |
| ADDITIV | /ES | | | | |
| Calcium | ppm | 49 | | | |
| Magnesium | ppm | <u> </u> | | | |
| Zinc | ppm | 66 | | | |
| Phosphorus | ppm | <u>571</u> | | | |
| Barium | ppm | 1 | | | |
| Boron | ppm | 2 | | | |
| | | | | | |



ALTA EQUIPMENT COMPANY

5210 REESE ROAD DAVIE, FL US 33314 Contact: N. FACEY nfacey@altaequipfl.com T: (954)581-4744 F: (954)583-0318

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The tin level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0095Unique No:10538572Signed:Don BaldridgeReport Date:04 Jul 2023



CONSTRUCTION EQUIPMENT





GRAPHS

