

CONSTRUCTION EQUIPMENT VOLVO A45G 342542 - DIESEL ENGINE



Sample No: VCP0007610

Oil Type: DIESEL ENGINE OIL SAE 30

Job No:

| VOLVO | | | | |
|------------------|------------|---------------|------|--|
| SAMPLE I | NFORMATION | | | |
| Sample Number | - | VCP0007610 | | |
| Sample Date | | 28 Jun 2023 | | |
| Machine Hours | | 0 | | |
| Oil Hours | | 6304 | | |
| Oil Changed | | N/A | | |
| Sample Status | | NORMAL | | |
| | | | | |
| OIL COND | ITION | | | |
| Visc @ 100°C | cSt | 12.3 | | |
| Base Number (BN) | mg KOH/g | ■ 8.4 | | |
| Oxidation (PA) | % | 67 | | |
| | | | | |
| CONTAMI | NATION | | | |
| CONTAMI | | | | |
| Soot % | % | ■ 0.3 | | |
| Nitration (PA) | % | 61 | | |
| Sulfation (PA) | % | 55 | | |
| Glycol | % | NEG | | |
| Fuel | % | ■0.2 | | |
| Silicon | ppm | ■ 5 | | |
| Sodium | ppm | 6 | | |
| Potassium | ppm | ■ 3 | | |
| VOLVO | | | | |
| WEAR ME | TALS | | | |
| Iron | ppm | ■8 | | |
| Copper | ppm | 5 | | |
| Lead | ppm | ■ <1 | | |
| Tin | ppm | ■<1 | | |
| Aluminum | ppm | ■ <1 | | |
| Chromium | ppm | - <1 | | |
| Molybdenum | ppm | ■58 | | |
| Nickel | ppm | ■<1 | | |
| Titanium | ppm | ■ <1 | | |
| Silver | ppm | 0 | | |
| Manganese | ppm | ■ <1 | | |
| Vanadium | ppm | <1 | | |
| | | | | |
| ADDITIVE | 22 | | | |
| Calcium | ppm | 1843 | | |
| Magnesium | ppm | 428 | | |
| Zinc | ppm | 1231 | | |
| Phosphorus | ppm | 1009 | | |
| Barium | ppm | ■ <1 | | |
| Boron | ppm | 3 | | |
| DOIOII | ppiii | | | |



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com T:

F: (904)737-1260

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 30. Please confirm.

All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0092

 Unique No:
 10546818

 Signed:
 Wes Davis

 Report Date:
 07 Jul 2023

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





GRAPHS

