CONSTRUCTION EQUIPMENT SW1020470 EWING IRRI VOLVO L50H 4322067 - HYDRAULICSY

Sample No:VCP406947Oil Type:AW HYDRAULIC OIL ISO 46Job No:SW1020470 EWING IRRI

VOLVO

VCP406947				
30 Jun 2023				
6239				
0				
Changed				
ATTENTION				
37.5				
0.32				
	30 Jun 2023 6239 0 Changed ATTENTION	30 Jun 2023 6239 0 Changed ATTENTION 37.5	30 Jun 2023 6239 0 Changed ATTENTION	30 Jun 2023 6239 0 Changed ATTENTION

CONTAMINATION Particles >4µm 5658 Particles >6µm 🔺 1316 Particles >14µm 79 20/18/13 ISO 4406:1999 (c) Silicon ppm 14 Sodium ppm 1 Potassium ppm 3

WEAR METALS

Iron	ppm	1 4	 	
Copper	ppm	5	 	
Lead	ppm	2	 	
Tin	ppm		 	
Aluminum	ppm	7	 	
Chromium	ppm		 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	 <1	 	
Vanadium	ppm	0	 	

	VC2			
Calcium	ppm	64	 	
Magnesium	ppm	3	 	
Zinc	ppm	443	 	
Phosphorus	ppm	339	 	
Barium	ppm	0	 	
Boron	ppm	0	 	



ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

. (002)+1+ 150-

Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO6174

 Unique No:
 10549389

 Signed:
 Don Baldridge


 Report Date:
 11 Jul 2023

CONSTRUCTION EQUIPMENT

VOLVO

GRAPHS





Report Id: VOLVO6174 [WUSCAR] 05893579 (Generated: 07/11/2023 14:24:22) Rev: 1

Contact/Location: RANDY PRZEKURAT - VOLVO6174