

Sample No: VCP406953
Oil Type: VOLVO WB 102

Job No: SW1020470 EWING IRR

SAMPLE	E INFORMATIO	N		
Sample Number	-	VCP406953	 	
Sample Date		30 Jun 2023	 	
Machine Hours		6239	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	NITION			
Visc @ 40°C		= E4.4	 	
VISC @ 40°C	cSt	■ 54.4	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	12	 	
Sodium	ppm	7	 	
Potassium	ppm	■ 3	 	
WEAR N	METALS			
Iron	ppm	■187	 	
Copper	ppm	■ 9	 	
Lead	ppm	■0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■ 2	 	
Molybdenum	ppm	■0	 	
Nickel	ppm	11	 	
Titanium	ppm	<1	 	
Silver	ppm	<1	 	
Manganese	ppm	■ 5	 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIV	VES			
Calcium	ppm	□3389	 	
Magnesium	ppm	10	 	
Zinc	ppm	■1375	 	
Phosphorus	ppm	■1157	 	
Barium	ppm	4	 	
Boron	ppm	125	 	
		_		



ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO6174Unique No:10549838Signed:Angela BorellaReport Date:12 Jul 2023



CONSTRUCTION EQUIPMENT





GRAPHS

