

## CONSTRUCTION EQUIPMENT 568198 VOLVO A30G 752866 - DIESEL ENGINE



Sample No: VCP422142

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

**Job No:** 568198

SAMPLE IN	NFORMATION			
	AF URMATION	VCD422442	VCD402062	 
Sample Number		VCP422142	VCP402963	
Sample Date		05 Jul 2023	13 Feb 2023	 
Machine Hours		1096	526	 
Oil Hours		500	526	 
Oil Changed		Changed	Changed	 
Sample Status		MARGINAL	ABNORMAL	 
VOLVO				
OIL CONDI	TION			
Visc @ 100°C	cSt	<b>12.3</b>	<u> </u>	 
Base Number (BN)		■8.7	6.2	 
Oxidation (PA)	%	77	59	 
VOLVO	IATION			
CONTAMIN				
Soot %	%	■ 0.4	■ 0.3	 
Nitration (PA)	%	72	82	 
Sulfation (PA)	%	63	54	 
Glycol	%	NEG	NEG	 
Fuel	%	<1.0	■ 0.6	 
Silicon	ppm	<b>7</b>	<b>46</b>	 
Sodium	ppm	<b>2</b>	■3	 
Potassium	ppm	<b>2</b>	<b>4</b>	 
VOLVO				
WEAR ME	7 IAT			
Iron		<b>12</b>	<u>27</u>	 
	ppm	▲ 123	△ 398	
Copper	ppm			 
Lead Tin	ppm	<b>■</b> 1	<1	 
i in Aluminum	ppm	<b>2</b>	<b>2</b>	 
	ppm		_	
Chromium	ppm	<b>■</b> <1	<b>-</b> <1	 
Molybdenum Nickel	ppm	<b>■</b> 52	■85 ■4	 
Nickei Titanium	ppm	<1	<1	 
Silver	ppm			 
	ppm	<b>■</b> <1	<b>=</b> <1	
Manganese	ppm	<b>■2</b> <1	<b>6</b>	 
Vanadium	ppm	<1	U	 
VOLVO				
ADDITIVE!	<u> </u>			
Calcium	ppm	<b>1698</b>	<b>□</b> 2118	 
Magnesium	ppm	■394	□134	 
		=		

**1210** 

**0** 

**2**4



## **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

## Diagnosis

Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level has decreased, but is still abnormal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:RIPTAMUnique No:10550577Signed:Jonathan HesterReport Date:11 Jul 2023

ppm

ppm

ppm

ppm

Zinc

Barium

Boron

Phosphorus

**1041** 

**845** 

**0** 

**28** 



## **CONSTRUCTION EQUIPMENT**





