

CONSTRUCTION EQUIPMENT 566012 VOLVO L110H 632273 - FRONT AXLE



Sample No: VCP393818
Oil Type: VOLVO WB 102

Job No: 566012

VOLVO CAMPIE	E INFORMATION			
Sample Number	- IMI OMPATION	VCP393818	VCP386239	
		20 Jun 2023	29 Nov 2022	
Sample Date Machine Hours		20 Jun 2023 2490	29 Nov 2022 1001	
Oil Charaged		1490	1000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	41.4	40.4	
		_		
VOLVO	AINIA TIONI			
LUNIAN	MINATION			
Silicon	ppm	16	■18	
Sodium	ppm	4	1 1	
Potassium	ppm	0	0	
WEAR N	AFTAI C			
_			5 244	
Iron	ppm	169	□314	
Copper	ppm	□ <1	1	
Lead 	ppm	0	<1	
Tin	ppm	0	<u> </u>	
Aluminum	ppm	2	_2	
Chromium	ppm	4	8	
Molybdenum	ppm	4	1 1	
Nickel	ppm	■ <1	0	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	■8	1 2	
Vanadium	ppm	0	0	
VOLVO				
ADDITIN	VES			
Calcium	ppm	□3458	□ 4193	
Magnesium	ppm	■ 10	13	
Zinc	ppm	■ 1527	1 1600	
Phosphorus	ppm	■ 1327 ■ 1256	1315	
Barium	ppm	■ 0	0	
Boron	ppm	35	143	
DOTOTI	ppiii	33	■ 14J	

Report Id: RIPTAM [WUSCAR] 05895393 (Generated: 07/12/2023 11:39:14) Rev: 1



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10551203Signed:Wes DavisReport Date:12 Jul 2023

Page 1 of 2



CONSTRUCTION EQUIPMENT





GRAPHS

