

CONSTRUCTION EQUIPMENT VOLVO L70H 622621 - COOLANT



Sample No: VCP0007997

Oil Type: HYBRID (HOAT) COOLANT

Job No:

FORMATION				
	VCD0007997			
	0			
	ABNORMAL			
CAMBITION				
LUNDITIUN				
Scale 0-14	■8.21			
Scale 0-20				
ppm	0			
%	△ 31.6			
°C	■ 3			
CONTRAGNATION				
CONTAMINATION				
	normal			
	Yllow			
	Scale 0-20 ppm % °C	VCP0007997 10 Jul 2023 0 ABNORMAL CONDITION Scale 0-14	VCP0007997 10 Jul 2023 0 ABNORMAL CONDITION Scale 0-14	VCP0007997 10 Jul 2023 0 ABNORMAL CONDITION Scale 0-14 ■8.21 Scale 0-20 ppm □ 0 % ▲ 31.6 °C □ 3 ATION normal



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

1:

F: (904)737-1260

Diagnosis

We recommend drain system, and refill with 50/50 antifreeze water mixture. There is no indication of any contamination in the coolant.
Carboxylate test failed. The glycol level is lower than acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO0092

 Unique No:
 10552459

 Signed:
 Doug Bogart

 Report Date:
 16 Jul 2023

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





GRAPHS

