

CONSTRUCTION EQUIPMENT

540989 DIPRO CATERPILLAR 982M LLSU02686 - DIESEL ENGINE

Sample No: VCP411765

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No: 540989 DIPRO

SAMPLE IN	NFORMATION			
Sample Number	-	VCP411765	VCP382971	
Sample Date		11 Jul 2023	19 Jan 2023	
Machine Hours		10846	10401	
Oil Hours		0	500	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ATTENTION	
OIT CONDI.	TION			
Visc @ 100°C	cSt	14.0	1 1.7	
Base Number (BN)	mg KOH/g	■9.4	■9.3	
Oxidation (PA)	%	63	90	

VOLVO	AIN A TION				
LUNIAN	MINATION		<u>_</u>		
Soot %	%	0.5	■ 0.9	 	
Nitration (PA)	%	63	88	 	
Sulfation (PA)	%	53	63	 	
Glycol	%	NEG	NEG	 	
Fuel	%	<1.0	■ 0.7	 	
Silicon	ppm	■ 4	6	 	
Sodium	ppm	1	2	 	
Potassium	ppm	1	_2	 	

Iron ppm 14 26 Copper ppm 2 4 Lead ppm 1 2 Tin ppm <1 Aluminum ppm 4 6 Chromium ppm <1 1 Molybdenum ppm 53 42 Nickel ppm 0 0 Titanium ppm 0 0 Silver ppm <1 0 Manganese ppm <1 <1 Vanadium ppm 0 0	WEAR	METALS			
Lead ppm 1 2 Tin ppm <1 Aluminum ppm 4 6 Chromium ppm 1 1 Molybdenum ppm 53 42 Nickel ppm 0 0 Titanium ppm 0 0 Silver ppm <1 0 Manganese ppm <1 <1	Iron	ppm	1 4	2 6	
Tin ppm Aluminum ppm 4 6 Chromium ppm 1 1 Molybdenum ppm 53 42 Nickel ppm 0 0 Titanium ppm 0 0 Silver ppm -1 0 Manganese ppm -1 -1	Copper	ppm	2	4	
Aluminum ppm 4 6 Chromium ppm <1	Lead	ppm	1	2	
Chromium ppm 1 Molybdenum ppm 53 42 Nickel ppm 0 0 Titanium ppm 0 0 Silver ppm <1	Tin	ppm	■ <1	 <1	
Molybdenum ppm 53 42 Nickel ppm 0 0 Titanium ppm 0 0 Silver ppm <1	Aluminum	ppm	4	6	
Nickel ppm 0 0 Titanium ppm 0 0 Silver ppm <1 0 Manganese ppm <1 <1	Chromium	ppm	■<1	1	
Titanium ppm 0 0 Silver ppm <1 0 Manganese ppm <1 <1	Molybdenum	ppm	■ 53	4 2	
Silver ppm 1 0 Manganese ppm 1 <1	Nickel	ppm	■0	0	
Manganese ppm	Titanium	ppm	0	□0	
	Silver	ppm	■<1	0	
Vanadium ppm 0 0	Manganese	ppm	■ < 1	< 1	
	Vanadium	ppm	0	0	

ADDIT	Zav			
Calcium	ppm	1099	■1739	
Magnesium	ppm	■907	501	
Zinc	ppm	1248	1135	
Phosphorus	ppm	1012	■940	
Barium	ppm	0	1	
Boron	ppm	4	2 5	



ALTA EQUIPMENT COMPANY - METRO WEST
56195 PONTIAC TRAIL

NEW HUDSON, MI
US 48165

Contact: PAUL CONZ
paul.conz@altg.com
T: (313)348-8861
F: (248)356-2029

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:VOLVO2990Unique No:10559732Signed:Don BaldridgeReport Date:17 Jul 2023



CONSTRUCTION EQUIPMENT





