

CONSTRUCTION EQUIPMENT

579651 DIPRO CATERPILLAR 972M HLSJ02687 - FRONT AXLE

Sample No: VCP414166
Oil Type: CAT TDTO 30W
Job No: 579651 DIPRO

VOLVO	LINEODMATIO	VI		
	E INFORMATIO	<u>.</u>		
Sample Number		VCP414166	VCP382969	
Sample Date		10 Jul 2023	19 Jan 2023	
Machine Hours		14435	12151	
Oil Hours		1000	2000	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	NORMAL	
OIL CON	IDITION			
Visc @ 40°C	cSt	■92.8	■88.4	
VOLVO				
CONTAI	MINATION			
Water	%	△ 0.231		
Silicon	ppm	1 5	3	
Sodium	ppm	■ 9	□ 5	
Potassium	ppm	2	2 3	
		_		
VOLVO	ACTAL C			
WEAR N	METAL2			
Iron	ppm	<u> </u>	7 5	
Copper	ppm	<u>^</u> 80	4	
Lead	ppm	 <1	4	
Tin	ppm	2	1	
Aluminum	ppm	10	< 1	
Chromium	ppm	6	1	
Molybdenum	ppm	■ 3	1	
Nickel	ppm	■ 3	1	
Titanium	ppm	<1	<1	
Silver	ppm	0	1	
Manganese	ppm	12	< 1	
Vanadium	ppm	0	<1	
ADDITIV	VES			
Calcium	ppm	■3273	□ 502	
Magnesium	ppm	■20	2 4	
Zinc	ppm	1381	■355	
Phosphorus	ppm	1140	270	
Barium	ppm	0	0	
Boron	ppm	■ 7	0	



ALTA EQUIPMENT COMPANY - METRO WEST
56195 PONTIAC TRAIL
NEW HUDSON, MI
US 48165
Contact: PAUL CONZ
paul.conz@altg.com
T: (313)348-8861
F: (248)356-2029

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.Bearing and/or gear wear is indicated. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO2990Unique No:10560321Signed:Don BaldridgeReport Date:17 Jul 2023



CONSTRUCTION EQUIPMENT





