

CONSTRUCTION EQUIPMENT X58251 VOLVO EC250ELR 310708 - REAR LEFT FINAL DRIVE

Sample No: VCP413447 Oil Type: **NOT GIVEN** Job No: X58251

SAMPLE	INFORMATIO	N			
Sample Number		VCP413447			
Sample Date		11 Jul 2023			
Machine Hours		2639			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		ABNORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	■302			
VOLVO	UNIA TION				
LUNIAN	INATION	,			
Silicon	ppm	<u> </u>			
Sodium	ppm	■ 5			
Potassium	ppm	■20			
VOLVO					
WEAR METALS					
Iron	ppm	<u>^</u> 736			
Copper	ppm	■ 2			
Lead	ppm	■0			
Tin	ppm	■ <1			
Aluminum	ppm	<u>▲</u> 52			
Chromium	ppm	<u> </u>			
Molybdenum	ppm	2			
Nickel	ppm	■ <1			
Titanium	ppm	3			
Silver	ppm	0			
Manganese	ppm	8			
Vanadium	ppm	<1			
VOLVO					
ADDITIV	IES				
Calcium	ppm	52			
Magnesium	ppm	7			
Zinc	ppm	25			
Phosphorus	ppm	954			
Barium	ppm	0			
Boron	ppm	73			



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997 SAINT ROSE, LA US 70087

Contact: DANA FOSHEE dfoshee@scottcompanies.com

T: (504)461-0961 F: (504)461-0970

Diagnosis

We advise that you check all areas where dirt can enter the system. Resample at the next service interval to monitor. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.

Depot: **SCOSAI Unique No:** 10560363 Signed: Don Baldridge Report Date: 17 Jul 2023



CONSTRUCTION EQUIPMENT





