

# CONSTRUCTION EQUIPMENT 361 CATERPILLAR DLSO 1977 - SWING DRIVE



Sample No: VCP418896

**Oil Type:** DRYDENE LIMITED SLIP GEAR 80W90

**Job No:** 361

VOLVO SAMPLE	INFORMATION				
Sample Number		VCP418896			
Sample Date		26 Jun 2023			
Machine Hours		6752			
Oil Changed		1000			
Oil Changed		Changed			
Sample Status		ABNORMAL			
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	<b>128</b>			
CONTAN	INATION				
Water	%	■ 0.193			
Silicon	ppm	■8			
Sodium	ppm	■0			
Potassium	ppm	<b>■&lt;1</b>			
VOLVO					
WEAR M	FTALS				
Iron		<b>□</b> 156			
Copper	ppm	■ <1			
Lead	ppm	<b>0</b>			
Tin	ppm	■0			
Aluminum	ppm	<b>■&lt;1</b>			
Chromium	ppm	■<1			
Molybdenum	ppm	<b>4</b>			
Nickel		■0			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	2			
Vanadium		<1			
variaululli	ppm	<b>\1</b>			
VOLVO					
<b>ADDITIV</b>	EZ				
Calcium	ppm	<b>821</b>			
Magnesium	ppm	<b>11</b>			
Zinc	ppm	<b>278</b>			
Phosphorus	ppm	<b>502</b>			
Barium	ppm	<b>0</b>			
Boron	ppm	<b>2</b>			



#### TOTAL DEVELOPMENT SOLUTIONS LLC

7805 PROGRESS CT
GAINESVILLE, VA
US 20155
Contact: JOE SEALE
jseale@totaldevelopmentsolutions.com
T: (703)222-0497
F: (703)753-4586

### Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:TOTGAIUnique No:10560822Signed:Don BaldridgeReport Date:18 Jul 2023

Contact/Location: JOE SEALE - TOTGAI



## **CONSTRUCTION EQUIPMENT**





#### GRAPH

