Sample No: VCP424873

Oil Type: MOBIL SHC 630

Job No: SPM579338

TAMPI	E INFORMATIOI	N		
				_
Sample Number		VCP424873	 	
Sample Date		15 Jul 2023	 	
Machine Hours		3003	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	202	 	
VOLVO				
CONTAI	MINATION			
Silicon	ppm	1 5	 	
Sodium	ppm	2	 	
Potassium	ppm	2	 	
WEAR	METALS			
WEAKI	METAL2			
Iron	ppm	■ 322	 	
Copper	ppm	<u></u> ▲ 61	 	
Lead	ppm	■ <1	 	
Tin	ppm	■3	 	
Aluminum	ppm	■3	 	
Chromium	ppm	4	 	
Molybdenum	ppm	■<1	 	
Nickel	ppm	■<1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
ADDITIV	VFS			
_		= 0.7		
Calcium	ppm	■87	 	
Magnesium	ppm	■ 0	 	
Zinc	ppm	■37	 	
Phosphorus	ppm	429	 	
Barium	ppm	■0	 	
Boron	ppm	■31	 	

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10563999Signed:Don BaldridgeReport Date:21 Jul 2023



CONSTRUCTION EQUIPMENT





