

# CONSTRUCTION EQUIPMENT VOLVO L70H 624135 - TRANSMISSION (AUTO)



Sample No: VCP412896

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No:

SAMPLI	E INFORMATION			
Sample Number	-	VCP412896	VCP357917	 
Sample Date		11 Jul 2023	22 Mar 2022	 
Machine Hours		2485	923	 
Oil Hours		0	923	 
Oil Changed		Changed	Not Changd	 
Sample Status		ABNORMAL	NORMAL	 
OIL CON	IDITION			
Visc @ 40°C	cSt	<b>26.5</b>	<b>□</b> 26.9	 
VISC @ 40 C	CSI	20.5		 
VOLVO				
CONTAI	MINATION			
Silicon	ppm	<b>11</b>	<b>□</b> 9	 
Sodium	ppm	<b>■</b> 8	<b>5</b>	 
Potassium	ppm	<b>■</b> 3	<b>0</b>	 
WEAR N	METALS			
Iron	ppm	<b>173</b>	<b>117</b>	 
Copper	ppm	<b>10</b>	<b>7</b>	 
Lead	ppm	<b>0</b>	<b>0</b>	 
Tin	ppm	<b>■&lt;1</b>	0	 
Aluminum	ppm	<b>5</b>	<b>2</b>	 
Chromium	ppm	<b>■</b> 1	<b>-</b> <1	 
Molybdenum	ppm	<b>■&lt;1</b>	<1	 
Nickel	ppm	<b>■&lt;1</b>	0	 
Titanium	ppm	0	0	 
Silver	ppm	<b>■</b> 0	<b>-</b> <1	 
Manganese	ppm	<b>12</b>	10	 
Vanadium	ppm	0	0	 
ADDITIV	VES			
Calcium	ppm	<b>□</b> 74	74	 
Magnesium	ppm	<b>■</b> 0	0	 
Zinc	ppm	<b>52</b>	44	 
Phosphorus	ppm	<b>165</b>	166	 
Barium	ppm	<b>■</b> 0	0	 
Darium	ppiii	<b>U</b>	O	



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T:

F: (239)481-3302

### Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The iron level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0090Unique No:10564031Signed:Don BaldridgeReport Date:21 Jul 2023



## **CONSTRUCTION EQUIPMENT**





