



CONSTRUCTION EQUIPMENT

SVC049435 VOLVO L60H 622420 - DIESEL FUEL



Sample No: VCP407150
Oil Type: NOT GIVEN
Job No: SVC049435



SAMPLE INFORMATION

Sample Number	VCP407150	---	---	---
Sample Date	18 Jul 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	ABNORMAL	---	---	---



FUEL CONDITION

Sulfur	ppm	0	---	---	---
Visc @ 40°C	cSt	2.59	---	---	---



CONTAMINATION

Water	%	0.006	---	---	---
Lead	ppm	<1	---	---	---
Nickel	ppm	0	---	---	---
Aluminum	ppm	<1	---	---	---
Vanadium	ppm	<1	---	---	---
Silicon	ppm	0	---	---	---



TYLER EQUIPMENT CORPORATION

1980 BERLIN TURNPIKE
BERLIN, CT
US 06037

Contact: KYLE SCHMITZ
kschmitz@tylerequipment.com
T: (860)356-0840
F: (860)828-6727

Diagnosis

We advise that you follow the water drain-off procedure for this component. We recommend you service and check the fuel filters for mucous-like deposits. Check with fuel supplier for biocides available to destroy the microorganisms in the fuel system. All metal levels are normal indicating no corrosion in the system. Excessive free water present. Moderate concentration of visible dirt/debris present in the fuel. Possible bacteria or fungus (yeast and/or mold) indicated in the sample. The condition of the fuel is acceptable for the time in service.

Depot: VOLVO0005
Unique No: 10564053
Signed: Doug Bogart
Report Date: 26 Jul 2023



CONSTRUCTION EQUIPMENT



GRAPHS

Pensky-Martens Flash Point (°C)

