

# CONSTRUCTION EQUIPMENT 23731 VOLVO L180H 5514 - REAR AXLE



Sample No: VCP420808
Oil Type: VOLVO WB 102

**Job No:** 23731

SAMPLE	E INFORMATIO	N		
Sample Number		VCP420808	 	
Sample Date		21 Jul 2023	 	
Machine Hours		4032	 	
Oil Hours		2000	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
		1101111111		
VOLVO	IDITION			
OIL CON		<u> </u>		
Visc @ 40°C	cSt	<b>42.3</b>	 	
CONTAN	MINATION			
Silicon		<b>1</b> 5	 	
Sodium	ppm	<b>8</b>	 	
Potassium	ppm		 	
Potassium	ppm	■ 0	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>■78</b>	 	
Copper	ppm	<b>5</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■</b> 3	 	
Molybdenum	ppm	<b>4</b>	 	
Nickel	ppm	<b>0</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>5</b>	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	<b>4074</b>	 	
Magnesium	ppm	<b>40</b>	 	
Zinc	ppm	<b>1733</b>	 	
Phosphorus	ppm	<b>1366</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>150</b>	 	



#### **MURRAY MINES**

2696 HIGHWAY 17A SUMMERVILLE, SC US 29483

Contact: SERVICE MANAGER

T: (843)875-7465 F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:MURSUMUnique No:10574604Signed:Wes DavisReport Date:27 Jul 2023



## **CONSTRUCTION EQUIPMENT**





