

CONSTRUCTION EQUIPMENT

567884 MOSAIC VOLVO EC380EL 314879 - SWING DRIVE

Sample No: VCP418307

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 567884 MOSAIC

VOLVO					
SAMPLE INFORMATION					
Sample Number	-	VCP418307			
Sample Date		28 Jun 2023			
Machine Hours		1116			
Oil Hours		1116			
Oil Changed		Changed			
Sample Status		SEVERE			
OIL CONDITION					
Visc @ 40°C	cSt	186			
VISC @ 40 C	CSI	100			
VOLVO					
CONTAM	INATION				
Water	%	△ 0.200			
Silicon	ppm	■27			
Sodium	ppm	2			
Potassium	ppm	■0			
WEAR METALS					
Iron	ppm	2722			
Copper	ppm	46			
Lead	ppm	0			
Tin	ppm	0			
Aluminum	ppm	■7			
Chromium	ppm	<u>^</u> 22			
Molybdenum	ppm	2			
Nickel	ppm	■<1			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	24			
Vanadium	ppm	<1			
ADDITIV	23				
Calcium	ppm	64			
Magnesium	ppm	4			
Zinc	ppm	■58			
Phosphorus	ppm	■394			
Barium	ppm	7			
Boron	ppm	■0			



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
JFARDELLA@ALTAEQUIPFL.COM
T: (813)630-0077
F: (813)630-2233

Diagnosis

The oil change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Gear wear is indicated. Appearance is hazy. There is a light concentration of water present in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:VOLVO0093Unique No:10574672Signed:Jonathan HesterReport Date:31 Jul 2023



CONSTRUCTION EQUIPMENT





