

CONSTRUCTION EQUIPMENT 10720 VOLVO L150G 23510 - FRONT AXLE



Sample No: VCP416444
Oil Type: NOT GIVEN

10720

Job No:

Phosphorus

Barium

Boron

ppm

ppm

ppm

VOLVO				
SAMPL	E INFORMATION			
Sample Number	-	VCP416444	VCP321600	
Sample Date		20 Jul 2023	15 Jun 2021	
Machine Hours		9618	4745	
Oil Hours		0	2000	
Oil Changed		Not Changd	Changed	
Sample Status		ABNORMAL	ABNORMAL	
VOLVO	IDITION			
	IDITION			
Visc @ 40°C	cSt	41.6	△ 40.8	
CONTA	MINATION			
_			- 45	
Silicon	ppm	1 5	15	
Sodium	ppm	3	4	
Potassium	ppm	■0	2	
VOLVO				
WEAR I	METALS			
Iron	ppm	□ 30	4 4	
Copper	ppm	■0	- <1	
Lead	ppm	■0	- <1	
Tin	ppm	■0	1	
Aluminum	ppm	■1	0	
Chromium	ppm	■<1	1	
Molybdenum	ppm	<1	<1	
Nickel	ppm	■0	0	
Titanium	ppm	0	<1	
Silver	ppm	0	<1	
Manganese	ppm	<1	1	
Vanadium	ppm	0	<1	
	PPIII			
VOLVO				
ADDITI	NEZ			
Calcium	ppm	3806	3965	
Magnesium	ppm	15	14	
Zinc	ppm	1572	1584	

1295



COVANTA ENERGY

10 HIGHLAND AVE CHESTER, PA US 19013 Contact: LOADER SHOP jacoles@covantaenergy.com T: (610)497-8115 F: (610)497-8042

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:COVCHEUnique No:10577009Signed:Sean FeltonReport Date:31 Jul 2023

1280

141

0



CONSTRUCTION EQUIPMENT





