CONSTRUCTION EQUIPMENT

Sample No:VCP414338Oil Type:DIESEL ENGINE OIL SAE 40Job No:64198 FIVE STONE

VOLVO

SAMPLE INFORMATION VCP414338 Sample Number Sample Date 26 Jul 2023 Machine Hours 702 Oil Hours 0 Oil Changed Changed SEVERE Sample Status **OIL CONDITION** Visc @ 40°C cSt 36.3 CONTAMINATION Silicon ppm 6 Sodium 2 ppm Potassium **||** <1 ppm WEAR METALS Iron ppm 38 Copper ppm 61 612 Lead ppm Tin ppm 1 Aluminum ppm 2 Chromium ppm ■ <1 Molybdenum **4** ppm Nickel ppm 0

 Titanium
 ppm
 0
 --- ---

 Silver
 ppm
 0
 --- ---

 Manganese
 ppm
 1
 --- ---

 Vanadium
 ppm
 0
 --- ---

Calcium	ppm	2594	 	
Magnesium	ppm	28	 	
Zinc	ppm	1134	 	
Phosphorus	ppm	927	 	
Barium	ppm	0	 	
Boron	ppm	18	 	



COWIN EQUIPMENT COMPANY INC - GUNTERSVILLE

15101 ALABAMA HWY 20 MADISON, AL US 35756 Contact: RANDY HARRIS RHARRIS@COWIN.COM T: (256)298-2322 F: (256)355-5250

Diagnosis

The fluid change at the time of sampling has been noted. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition.Clutch wear is indicated. There is no indication of any contamination in the fluid. The fluid is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:COWMADUnique No:10585710Signed:Jonathan HesterReport Date:04 Aug 2023

Contact/Location: RANDY HARRIS - COWMAD

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

