



# CONSTRUCTION EQUIPMENT

ASCENDUM MACHINERY 19248 VOLVO L150H RL72 (S/N 7053) - REAR AXLE



**Sample No:** VCP412182  
**Oil Type:** VOLVO WB 102  
**Job No:** 19248



## SAMPLE INFORMATION

Sample Number	VCP412182	---	---	---
Sample Date	20 Jul 2023	---	---	---
Machine Hours	3645	---	---	---
Oil Hours	3645	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

### HILCO TRANSPORT

7700 KENMONT RD  
GREENSBORO, NC  
US 27409  
Contact: MIKE LAUGHEAD  
mlaughead@hilcotransport.com  
T: (336)273-9441  
F: (336)273-9701



## OIL CONDITION

Visc @ 40°C	cSt	█ 42.2	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 15	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 1	---	---	---



## WEAR METALS

Iron	ppm	█ 34	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 5	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 3959	---	---	---
Magnesium	ppm	█ 27	---	---	---
Zinc	ppm	█ 1642	---	---	---
Phosphorus	ppm	█ 1314	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 137	---	---	---

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** HILGREVC  
**Unique No:** 10587585  
**Signed:** Doug Bogart  
**Report Date:** 06 Aug 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

