


## **CONSTRUCTION EQUIPMENT** SWA319807

VOLVO EC350EL 314349 - DIESEL ENGINE







#### **ALTA EQUIPMENT**

5985 COURT STREET ROAD SYRACUSE, NY US 13206 Contact: JIM STRIGLE JIM.STRIGLE@ALTG.COM T: (315)437-2611 F: (315)434-9471

### Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. The copper level is abnormal. All other component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0142 **Unique No:** 10602704 Signed: Don Baldridge **Report Date:** 15 Aug 2023

ppm

Boron

**12** 



# **CONSTRUCTION EQUIPMENT**





