

## **CONSTRUCTION EQUIPMENT**

SWO 064468 VOLVO EC200EL 314424 - REAR RIGHT FINAL DRIV

Sample No: VCP426963

Oil Type: COWIN 80W90

Job No: SWO 064468

VOLVO	INFORMATIO	N		
	INFUKMATIU	<u> </u>		_
Sample Number		VCP426963	 	
Sample Date		09 Aug 2023	 	
Machine Hours		1995	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>166</b>	 	
VISC @ 40 C	CSI	<b>100</b>	 	
VOLVO				
CONTAM	IINATION			
Silicon	ppm	<u>^</u> 97	 	
Sodium	ppm	■0	 	
Potassium	ppm	<b>2</b>	 	
WEAR M	ETALC			
WEAR M	IC I WF7			
Iron	ppm	<u>^</u> 507	 	
Copper	ppm	<b>■</b> <1	 	
Lead	ppm	■0	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>■</b> 7	 	
Chromium	ppm	<b>6</b>	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<b>2</b>	 	
Titanium	ppm	1	 	
Silver	ppm	0	 	
Manganese	ppm	6	 	
Vanadium	ppm	0	 	
VOLVO				
<b>ADDITIV</b>	ES			
Calcium	ppm	14	 	
Magnesium	ppm	0	 	
Zinc	ppm	14	 	
Phosphorus	ppm	74	 	
Barium	ppm	2	 	
Boron	ppm	0	 	



## **COWIN EQUIPMENT COMPANY**

7950 PITTMAN AVE
PENSACOLA, FL
US 32534
Contact: HUGH DOBBS
HDOBBS@COWIN.COM
T: (850)479-3004
F: (850)474-1602

## Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Gear wear is indicated. Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8247Unique No:10603723Signed:Doug BogartReport Date:15 Aug 2023



## **CONSTRUCTION EQUIPMENT**





