Sample No: VCP409486

Oil Type: TDTO FLUID SAE 50

Job No: SWA 311337 RANJO

VOLVO	INFORMATION			
	INFORMATION			
Sample Number		VCP409486	VCP403213	
Sample Date		04 Aug 2023	07 Feb 2023	
Machine Hours		9578	8116	
Oil Hours		0	0	
Oil Changed		Changed	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL COND	DITION			
Visc @ 40°C	cSt	188	■186	
CONTAM	INATION			
Silicon	ppm	11	9	
Sodium	ppm	■0	2	
Potassium	ppm	1	0	
VOLVO				
WEAR M	ETALS			
Iron	ppm	■ 53	28	
Copper	ppm	■ <1	- <1	
Lead	ppm	0		
Tin	ppm	■ 0	- <1	
Aluminum	ppm	2	0	
Chromium	ppm	■ <1	- <1	
Molybdenum	ppm	■ <1	- <1	
Nickel	ppm	■<1	- <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	- <1	<u> </u>	
Vanadium	ppm	0	0	
ADDITIV	ES			
Calcium	ppm	2522	2571	
Magnesium	ppm	11	1 5	
Zinc	ppm	1079	<u></u> 1070	
Phosphorus	ppm	948	918	
Barium	ppm	2	<u></u> 0	
Boron	ppm	11	8	

ALTA CONSTRUCTION EQUIPMENT

613 E STEVENSON RD
OTTAWA, IL
US 61350
Contact: ALEX MARCO
ALEXANDER.MARCO@ALTG.COM
T:

F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO5055Unique No:10603730Signed:Wes DavisReport Date:15 Aug 2023



CONSTRUCTION EQUIPMENT





