Sample No: VCP409484
Oil Type: VOLVO WB 102

Job No: SWA 311337 RANJO

VOLVO				
SAMPLE	E INFORMATIO	N		
Sample Number		VCP409484	 	
Sample Date		04 Aug 2023	 	
Machine Hours		9578	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>41.7</b>	 	
CUNTAR	MINATION			
_	-			
Silicon	ppm	23	 	
Sodium	ppm	<b>6</b>	 	
Potassium	ppm	<b>2</b>	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>65</b>	 	
Copper	ppm	<b>■</b> 98	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	4	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>■&lt;1</b>	 	
Nickel	ppm	<b>4</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	■3444	 	
Magnesium	ppm	<b>12</b>	 	
Zinc	ppm	<b>1404</b>	 	
Phosphorus	ppm	<b>1209</b>	 	
Barium	ppm	<b>2</b>	 	
Boron	ppm	<b>120</b>	 	
		<del>-</del>		

## **ALTA CONSTRUCTION EQUIPMENT**

613 E STEVENSON RD
OTTAWA, IL
US 61350
Contact: KEVIN SKRTICH
KEVIN.SKRTICH@ALTAEQUIPMENT.COM

T: F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO5055Unique No:10603732Signed:Don BaldridgeReport Date:15 Aug 2023



## **CONSTRUCTION EQUIPMENT**





