

# CONSTRUCTION EQUIPMENT SWA 311337 RANJO VOLVO A60H 350076 - REAR AXLE

Sample No: VCP409485

Oil Type: **TDTO FLUID SAE 50** Job No: **SWA 311337 RANJO** 

SAMPLE	INFORMATION	N			
Sample Number		VCP409485			
Sample Date		04 Aug 2023			
Machine Hours		9578			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>186</b>			
VISC & 10 C	COC				
VOLVO					
LONTAM	IINATION				
Silicon	ppm	■8			
Sodium	ppm	■0			
Potassium	ppm	<b>1</b>			
WEAR M	IETALS				
Iron	ppm	<b>29</b>			
Copper	ppm	<b>■&lt;1</b>			
Lead	ppm	■0			
Tin	ppm	■0			
Aluminum	ppm	<b>2</b>			
Chromium	ppm	<b>■&lt;1</b>			
Molybdenum	ppm	<b>■</b> <1			
Nickel	ppm	<b>■&lt;1</b>			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	<b>■</b> <1			
Vanadium	ppm	0			
VOLVO					
ADDITIV	ES				
Calcium	ppm	■2566			
Magnesium	ppm	<b>13</b>			
Zinc	ppm	<b>1085</b>			
Phosphorus	ppm	■954			
Barium	ppm	<b>2</b>			
Boron	ppm	<b>■</b> 9			

#### **ALTA CONSTRUCTION EQUIPMENT**

613 E STEVENSON RD OTTAWA, IL US 61350 Contact: ALEX MARCO ALEXANDER.MARCO@ALTG.COM T:

### Diagnosis

F:

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO5055 **Unique No:** 10603733 Signed: Wes Davis Report Date: 15 Aug 2023



## **CONSTRUCTION EQUIPMENT**





