

CONSTRUCTION EQUIPMENT 133988 VOLVO EC750E 314191 - LEFT SWING DRIVE



Sample No: VCP416019

Oil Type: GEAR OIL SAE 80W90

Job No: 133988

CVMDIE	INFORMATION				
	INFURMATION		1407440700		1/65/10/1000
Sample Number		VCP416019	VCP418720	VCP410104	VCP401900
Sample Date		08 Aug 2023	20 Jun 2023	17 Apr 2023	20 Feb 2023
Machine Hours		2037	1596	985	488
Oil Hours		0	0	0	0
Oil Changed		Changed	Not Changd	Changed	Changed
Sample Status		NORMAL	NORMAL	ABNORMAL	NORMAL
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	128	127	132	172
	CSt		<u> </u>		.,,_
VOLVO					
LUNTAM	IINATION				
Silicon	ppm	3	1	2	7
Sodium	ppm	1	0	0	2
Potassium	ppm	□ <1	< 1	0	- <1
WEAR M	ETALS				
Iron	ppm	■89	5 1	■85	□ 205
Copper	ppm	4	2	5	□13
Lead	ppm	■ 0	0	0	- <1
Tin	ppm	■<1	0	0	0
Aluminum	ppm	1	0	< 1	2
Chromium	ppm	1	 <1	- <1	4
Molybdenum	ppm	0	 <1	2	<1
Nickel	ppm	0	- <1	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	<1
Manganese	ppm	1	< 1	1	3
Vanadium	ppm	0	0	0	0
VOLVO					
ADDITIV	ES				
Calcium	ppm	7 0	68	□98	6
Magnesium	ppm	2	- <1	7	<1
Zinc	ppm	46	4 5	□ 56	19
Phosphorus	ppm	954	972	■869	274
Barium	ppm	0	0	□0	3
Boron	ppm	163	195	163	0



LATTIMORE MATERIALS/HOLCIM - ROSSER - LAFARGE 14242 S SH-34 SCURRY, TX US 75158 Contact: WALLACE WARREN wallace.warren@lafargeholcim.com T: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:LATSCUUnique No:10603758Signed:Jonathan HesterReport Date:16 Aug 2023



CONSTRUCTION EQUIPMENT





