

## CONSTRUCTION EQUIPMENT W07013061 VOLVO L60H 622656 - FRONT AXLE



Sample No: VCP409413

Oil Type: VOLVO WB 102

Job No: WO7013061

SAMPLE	E INFORMATION	I		
Sample Number		VCP409413	VCP396516	 
Sample Date		02 Aug 2023	10 Feb 2023	 
Machine Hours		2364	1522	 
Oil Hours		2000	1522	 
Oil Changed		Not Changd	Changed	 
Sample Status		NORMAL	NORMAL	 
OIL CON	DITION			
Visc @ 40°C	cSt	<b>43.1</b>	<b>40.1</b>	 
VOLVO	MINISTION			
LUNIAN	MINATION			
Silicon	ppm	<b>15</b>	<b>1</b> 3	 
Sodium	ppm	<b>■&lt;1</b>	■8	 
Potassium	ppm	<b>0</b>	■3	 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>17</b>	<b>7</b> 0	 
Copper	ppm	■0	2	 
Lead	ppm	<b>■&lt;1</b>	<b>0</b>	 
Tin	ppm	<b>■</b> 0	0	 
Aluminum	ppm	<b>■&lt;1</b>	< 1	 
Chromium	ppm	<b>■&lt;1</b>	<b>3</b>	 
Molybdenum	ppm	<b>■&lt;1</b>	<b>2</b>	 
Nickel	ppm	<b>■</b> 0	0	 
Titanium	ppm	0	0	 
Silver	ppm	0	0	 
Manganese	ppm	<b>1</b>	<b>7</b>	 
Vanadium	ppm	0	0	 
ADDITIV	VES			
Calcium	ppm	<b>4001</b>	■3999	 
Magnesium	ppm	<b>1</b> 3	12	 
Zinc	ppm	<b>1648</b>	<b>1641</b>	 
Phosphorus	ppm	<b>1262</b>	<b>1305</b>	 
Barium	ppm	<b>0</b>	<b>0</b>	 
Boron	ppm	<b>149</b>	<b>1</b> 42	 



McClung-Logan Virginia LLC- RICHMOND
1345 MOUNTAIN ROAD
GLEN ALLEN, VA
US 23060
Contact: KYLE RATLIFFE
KRATLIFFE@MCCLUNG-LOGAN.COM
T:
F: (804)266-1611

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8882Unique No:10604473Signed:Sean FeltonReport Date:15 Aug 2023



## **CONSTRUCTION EQUIPMENT**





