

# CONSTRUCTION EQUIPMENT VOLVO EC60 315303 - DIESEL ENGINE



Sample No: VCP415949

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

Job No:

VOLVO	INFORMATION			
	INFORMATION			
Sample Number		VCP415949	 	
Sample Date		27 Jul 2023	 	
Machine Hours		563	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL COND	ITION			
Visc @ 100°C	cSt	<b>13.9</b>	 	
Base Number (BN)		<b>■</b> 6.6	 	
Oxidation (PA)	%	69	 	
Chidation (171)	70	<b>U</b>		
VOLVO				
CONTAM	INATION			
Soot %	%	■ 0.2	 	
Nitration (PA)	%	87	 	
Sulfation (PA)	%	61	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	
Silicon	ppm	<b>11</b>	 	
Sodium	ppm	<b>5</b>	 	
Potassium	ppm	<b>■</b> 3	 	
WEAR M	FTAIS			
_	<del></del>			
Iron	ppm	<b>23</b>	 	
Copper	ppm	<b>102</b>	 	
Lead	ppm	<b>■ &lt;1</b>	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>■</b> 3	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	■23	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	<b>■</b> 0	 	
Manganese	ppm	<b>■</b> 3	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	<b>2364</b>	 	
Magnesium	ppm	309	 	
Zinc	ppm	<b>1260</b>	 	
Phosphorus	ppm	998	 	
Barium		<b>1</b>	 	
Boron	ppm	<b>8</b>	 	
DOTOIT	ppm	<b>O</b>	 	

#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: ROBERT TURNER rturner@ripatampa.com T: F:

### Diagnosis

Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:RIPTAMUnique No:10605793Signed:Wes DavisReport Date:17 Aug 2023



## **CONSTRUCTION EQUIPMENT**





