

# CONSTRUCTION EQUIPMENT VOLVO A40G 352973 - WET DISC BRAKE



Sample No: VCP421323

Oil Type: VOLVO WET BRAKE TRANSAXLE OIL

Job No:

VOLVO	INCODMATIO	N		
	INFORMATIO			
Sample Number		VCP421323	 	
Sample Date		04 Aug 2023	 	
Machine Hours		1903	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	NITION			
		= 40.0		
Visc @ 40°C	cSt	<b>40.9</b>	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	<b>1</b> 9	 	
Sodium	ppm	■9	 	
Potassium	ppm	<b>■&lt;1</b>	 	
	ρρ			
VOLVO				
WEAR N	METALS			
Iron	ppm	■20	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b></b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>4</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>2</b>	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	■3542	 	
Magnesium	ppm	<b>11</b>	 	
Zinc	ppm	<b>■</b> 1553	 	
Phosphorus	ppm	<b>1271</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	92	 	
DOTOIT	Phili	■ JL		



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

### Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10606380Signed:Don BaldridgeReport Date:17 Aug 2023



## **CONSTRUCTION EQUIPMENT**





