

# CONSTRUCTION EQUIPMENT VOLVO A40G 352410 - WET DISC BRAKE



Sample No: VCP412144
Oil Type: VOLVO WB 102

Job No:

INFORMATION				
-	VCP412144	VCP329170	VCP296000	
	09 Aug 2023	30 Sep 2021	23 Dec 2020	
	3913	2118	1113	
	0	0	0	
	Changed	Changed	Not Changd	
	ABNORMAL	ABNORMAL	ABNORMAL	
ITION				
cSt	<b>44.0</b>	<b>■</b> 39.8	■39.7	
INATION				
INATIUN				
ppm	_			
ppm			_	
ppm	<b>■</b> <1	<b>-</b> <1	<b>4</b>	
ETALS				
ppm	<b>19</b>	<b>1</b> 7	<b>1</b> 1	
ppm	<u></u> 4 364	<u>▲</u> 212	<u></u> 104	
ppm	<b>■</b> 0		<b>2</b>	
ppm	<b>■&lt;1</b>	<b>-</b> <1	<b>0</b>	
ppm	<b>2</b>	<b>1</b>	<b>1</b>	
ppm	<b>■&lt;1</b>	<b>-</b> <1	<b>=</b> <1	
ppm	■0	<b>&lt;</b> 1	□0	
ppm	_			
ppm	_			
ppm	_			
ppm	<b>2</b>	_	_	
ppm	0	0	0	
23				
ppm	■3401	■3607	■4004	
ppm	<b>16</b>	<b>1</b> 0	<b>1</b> 0	
ppm	■1306	■1452	<b>1657</b>	
ppm	<b>1163</b>	■1253	<b>1287</b>	
		_	_	
ppm	<b>0</b>	<b>0</b>	<b>0</b>	
	ppm	VCP412144  09 Aug 2023  3913  0 Changed  ABNORMAL  INATION  cSt	VCP412144         VCP329170           09 Aug 2023         30 Sep 2021           3913         2118           0         0           Changed         Changed           ABNORMAL         ABNORMAL           INATION         39.8           INATION         39.8           INATION         15         18           ppm         4         12           ppm         4         12           ppm         364         212           ppm         0         <1	VCP412144         VCP329170         VCP296000           09 Aug 2023         30 Sep 2021         23 Dec 2020           3913         2118         1113           0         0         0           Changed         Not Changd           ABNORMAL         ABNORMAL         ABNORMAL           ITION           CST         44.0         39.8         39.7           INATION           Ppm         15         18         18           ppm         4         12         12           ppm         4         12         12           ppm         364         212         104           ppm         364         212         104           ppm         <1



#### **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

### Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10606387Signed:Don BaldridgeReport Date:17 Aug 2023



## **CONSTRUCTION EQUIPMENT**





#### GRAPHS

