

CONSTRUCTION EQUIPMENT VOLVO A45G 342539 - COOLANT



Sample No:VCP0007501Oil Type:{unknown}

Job No:

SAMPLE IN	FORMATION				
Sample Number	-	VCP0007501			
Sample Date		11 Aug 2023			
Machine Hours		0			
Sample Status		ABNORMAL			
COOLANT CONDITION					
рН	Scale 0-14	8.01			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	NT			
Percentage Glycol	%	<u> </u>			
Freezing Point	°C	15			
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Yllow			



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256 Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com T: F: (904)737-1260

Diagnosis

We recommend drain system, and refill with 50/50 antifreeze water mixture. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is lower than acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO0092

 Unique No:
 10606472

 Signed:
 Jonathan Hester

 Report Date:
 18 Aug 2023

Submitted By: TECHNICIAN ACCOUNT

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

