CONSTRUCTION EQUIPMENT VOLVO EC380EL 314998 - SWING DRIVE X58407



Sample No:	VCP413461	
Oil Type:	NOT GIVEN	
Job No:	X58407	

Boron

VOLVO

SAMPLE	INFORMATION		 	
Sample Number		VCP413461	 	
Sample Date		11 Aug 2023	 	
Machine Hours		1084	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON				
Visc @ 40°C	cSt	172	 	
CONTAM	IINATION			
Silicon	ppm	9	 	
Sodium	ppm	2	 	
Potassium	ppm	□ <1	 	
WEAR M	IETALS			
Iron	ppm	431	 	
Copper	ppm	18	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	3	 	
Chromium	ppm	5	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	6	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	ES			
Calcium	ppm	8	 	
Magnesium	ppm	4	 	
Zinc	ppm	32	 	
Phosphorus	ppm	317	 	
Barium	ppm	4	 	



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997 SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961

F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: SCOSAI Unique No: 10606832 Signed: Jonathan Hester Report Date: 18 Aug 2023

0


ppm

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: SCOSAI [WUSCAR] 05926885 (Generated: 08/18/2023 11:40:36) Rev: 1

Contact/Location: DENISE CORVERS - SCOSAI