

CONSTRUCTION EQUIPMENT SENNEBOGEN 840ME 840.0.2170 - FRONT AXLE



Sample No: VCP396697 **Oil Type:**

ADDITIVES

ppm

ppm

ppm

ppm

ppm

ppm

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

GEAR OIL SAE 80W90

Job No:

14 850 0 Ch NC	Aug 2023 08 anged	VCP344706 08 Oct 2021 4315 0 Not Changd NORMAL	 	
14 850 0 Ch NC	Aug 2023 08 anged	08 Oct 2021 4315 0 Not Changd	 	
850 0 Ch NC	08 anged	4315 0 Not Changd		
0 Ch NC	anged	0 Not Changd		
Ch. NC	anged	Not Changd		
	-	0		
	ORMAL	NORMAL		
t 🗖	146	148		
_		_		
ON				
m 📃	2	0		
m 📃	0	0		
m 🔲	0	0		
2				
m 🔲	2	2		
m 📃	0	0		
m 📃	0	0		
m 📃	0	0		
m 📃	0	0		
m 📃	0	0		
m 📃	0	0		
m 📃	0	0		
m	0	0		
m	0	0		
m 📃	0	<1		
m	0	0		
	DN m I m I m I m I m I m I m I m I m I m I	DN m 2 m 0 m 0 m 0 m 2 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0 m 0	Image: Constraint of the second se	Imm 2 0 m 0 m 0

0

0

5

0

1862

186

ALTA CONSTRUCTION EQUIPMENT

613 E STEVENSON RD OTTAWA, IL US 61350 Contact: ALEX MARCO ALEXANDER.MARCO@ALTG.COM T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	VOLVO5055
Unique No:	10609004
Signed:	Sean Felton
Report Date:	21 Aug 2023

3

1

5

0

2103


166

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO5055 [WUSCAR] 05929057 (Generated: 08/21/2023 16:45:56) Rev: 1

Contact/Location: ALEX MARCO - VOLVO5055