

## CONSTRUCTION EQUIPMENT VOLVO A30G 742515 - FRONT AXLE



Sample No: VCP412958

Oil Type: CHEVRON MULTIGEAR EP5 80W90

Job No:

SAMPLE	INFORMATION				
Sample Number	_	VCP412958			
Sample Date		17 Aug 2023			
Machine Hours		2000			
Oil Hours		1000			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>126</b>			
VISC @ 40 C	CSt				
VOLVO					
CONTAN	MINATION				
Silicon	ppm	<b>1</b>			
Sodium	ppm	<b>1</b>			
Potassium	ppm	<b>0</b>			
WEAR METALS					
Iron	ppm	<b>7</b> 5			
Copper	ppm	<b>2</b>			
Lead	ppm	<b>0</b>			
Tin	ppm	<b>0</b>			
Aluminum	ppm	<b>■&lt;1</b>			
Chromium	ppm	<b>1</b>			
Molybdenum	ppm	■3			
Nickel	ppm	<b>■&lt;1</b>			
Titanium	ppm	1			
Silver	ppm	0			
Manganese	ppm	<b>2</b>			
Vanadium	ppm	<1			
VOLVO					
ADDITIV	/ES				
Calcium	ppm	<b>113</b>			
Magnesium	ppm	<b>47</b>			
Zinc	ppm	<b>7</b> 4			
Phosphorus	ppm	<b>976</b>			
Barium	ppm	<b>0</b>			
Boron	ppm	<b>187</b>			



DH FUNK AND SONS LLC 3995 CONTINENTAL DRIVE COLUMBIA, PA US 17512 Contact: GARY SHEPHERD GSHEPHERD@DHFUNK.COM

T: F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: DHFCOL
Unique No: 10615314
Signed: Sean Felton
Report Date: 23 Aug 2023



## **CONSTRUCTION EQUIPMENT**





