

CONSTRUCTION EQUIPMENT VOLVO A30G 742515 - BRAKE



Sample No: VCP412962

Oil Type: OEM

Job No:

SAMPLE	E INFORMATIO	N		
Sample Number	_	VCP412962	 	
Sample Date		17 Aug 2023	 	
Machine Hours		2000	 	
Oil Hours		2000	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	NITION			
Visc @ 40°C		= 20.5	 	
Visc @ 40°C	cSt	■39.5	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	1 4	 	
Sodium	ppm	■8	 	
Potassium	ppm	1	 	
WEAR M	METALS			
Iron	ppm	16	 	
Copper	ppm	△ 443	 	
Lead	ppm	■4	 	
Tin	ppm	■<1	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	■1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	
VOLVO				
ADDITIV	VES			
Calcium	ppm	3220	 	
Magnesium	ppm	9	 	
Zinc	ppm	1336	 	
Phosphorus	ppm	1178	 	
Barium	ppm	0	 	
Boron	ppm	120	 	



DH FUNK AND SONS LLC 3995 CONTINENTAL DRIVE COLUMBIA, PA US 17512 Contact: GARY SHEPHERD GSHEPHERD@DHFUNK.COM

T: F:

Diagnosis

The fluid change at the time of sampling has been noted. Resample at the next service interval to monitor. The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:DHFCOLUnique No:10615315Signed:Jonathan HesterReport Date:23 Aug 2023



CONSTRUCTION EQUIPMENT





GRAPHS

