

CONSTRUCTION EQUIPMENT VOLVO EC220EL 314469 - SWING DRIVE



Sample No: VCP411611

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No:

CAMDIE	INFORMATIO	1		
	. INFURMATIUI		_	
Sample Number		VCP411611	VCP354443	
Sample Date		15 Aug 2023	24 Jul 2022	
Machine Hours		931	334	
Oil Hours		0	334	
Oil Changed		Not Changd	Not Changd	
Sample Status		SEVERE	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	191	178	
V13C @ 40 C	CSt	131	170	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	47	2 2	
Sodium	ppm	4	- <1	
Potassium	ppm	1	1	
VOLVO	IFTALC			
WEAR N	IE I ALS			
Iron	ppm	3732	■840	
Copper	ppm	<u></u> ▲ 63	1 3	
Lead	ppm	■0	□0	
Tin	ppm	■ <1	0	
Aluminum	ppm	■8	2	
Chromium	ppm	• 44	8	
Molybdenum	ppm	■4	<1	
Nickel	ppm	1	0	
Titanium	ppm	1	0	
Silver	ppm	0	0	
Manganese	ppm	■ 36	10	
Vanadium	ppm	<1	0	
VOLVO				
ADDITIV	/ES			
Calcium	ppm	■ 10	4	
Magnesium	ppm	■ 3	<1	
Zinc	ppm	■ 52	20	
Phosphorus	ppm	■ 664	337	
Barium	ppm	12	0	
Boron	ppm	<u> </u>	5	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

We recommend that you drain the oil from the component if this has not already been done. We advise that you inspect for the source(s) of wear. We recommend an early resample to monitor this condition. Bearing and/or gear wear is indicated. There is no indication of any contamination in the oil. The oil is no longer serviceable as a result of the abnormal and/or severe wear.

Depot:VOLVO0093Unique No:10615338Signed:Jonathan HesterReport Date:23 Aug 2023

Contact/Location: KENNY HANEY - VOLVO0093



CONSTRUCTION EQUIPMENT





