

Sample No: VCP368369
Oil Type: NOT GIVEN

Job No: CEDAR RIDGE DAIRY

VOLVO CAMPI	E INFORMATIO	N		
Sample Number		VCP368369	 	
Sample Number		16 Aug 2023	 	
Machine Hours		3702	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
Sample Status		ADITORIVIAL		
VOLVO				
OIL CON	IDITION			
Visc @ 40°C	cSt	■28.0	 	
TONTA	MINATION			
_		-40	 <u> </u>	
Silicon	ppm	<b>12</b>	 	
Sodium	ppm	<u>5</u>	 	
Potassium	ppm	■3	 	
VOLVO				
WEAR I	METALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	<b>156</b>	 	
Lead	ppm	■0	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<u></u> <1	 	
Chromium	ppm	<b>-&lt;1</b>	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	<b>-&lt;1</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	8	 	
Vanadium	ppm	0	 	
ADDITI	VEC			
_		200		
Calcium	ppm	323	 	
Magnesium	ppm	5	 	
Zinc	ppm	133	 	
Phosphorus	ppm	299	 	
Barium	ppm	0	 	
Boron	ppm	90	 	



## ARNOLD MACHINERY COMPANY 464 WASHINGTON STREET S TWIN FALLS, ID US 83301

Contact: JANAE HYMAS jhymas@arnoldmachinery.com T: (208)733-1715

F: (775)356-7152

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The iron level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO1835Unique No:10617046Signed:Don BaldridgeReport Date:24 Aug 2023



## **CONSTRUCTION EQUIPMENT**





