

# CONSTRUCTION EQUIPMENT RSO-034991 FREIGHTLINER WT-4204 - REAR AXLE



Sample No: VCP427343

**Oil Type:** GEAR OIL SAE 75W90

**Job No:** RSO-034991

SAMPLE	INFORMATION			
Sample Number		VCP427343	 	
Sample Date		16 Aug 2023	 	
Machine Hours		2061	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	■92.5	 	
VOLVO	UNATION			
_	<u> </u>			
Silicon	ppm	<b>■</b> 9	 	
Sodium	ppm	<b>■</b> 4	 	
Potassium	ppm	■3	 	
VOLVO				
<b>WEAR</b> W	IETALS			
Iron	ppm	<b>100</b>	 	
Copper	ppm	<b>■</b> <1	 	
Lead	ppm	<b>■</b> 0	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>1</b>	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	<b></b>	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	<1	 	
Manganese	ppm	■8	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	ES			
Calcium	ppm	<b>1</b> 9	 	
Magnesium	ppm	<b>■</b> 5	 	
Zinc	ppm	<b>15</b>	 	
Phosphorus	ppm	<b>1376</b>	 	
Barium	ppm	■0	 	
Boron	ppm	<b>290</b>	 	

### SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207 Contact: STEPHANI BRITTON

sbritton@saiia.com;doug.bogart@wearcheck.com

T: (205)943-2268 F: (205)943-2269

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SAIBIRUnique No:10617655Signed:Jonathan HesterReport Date:25 Aug 2023



# **CONSTRUCTION EQUIPMENT**





### **GRAPHS**

