

# CONSTRUCTION EQUIPMENT RSO-034991 FREIGHTLINER WT-4204 - COOLANT



Sample No: VCP427475

Oil Type: NOT GIVEN

Job No: RSO-034991

SAMPLE INFORMATION					
Sample Number	-	VCP427475			
Sample Date		16 Aug 2023			
Machine Hours		2061			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	<b>7.27</b>			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	■NT			
Percentage Glycol	%	<b>■51.2</b>			
Freezing Point	°C	<b>■-38</b>			
VOLVO					
CONTAMINATION					
Coolant Appearance		normal			
Coolant Color		Orange			

#### SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD BIRMINGHAM, AL US 35207

Contact: STEPHANI BRITTON sbritton@saiia.com;doug.bogart@wearcheck.com

T: (205)943-2268 F: (205)943-2269

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SAIBIRUnique No:10617793Signed:Doug BogartReport Date:26 Aug 2023



# **CONSTRUCTION EQUIPMENT**





### **GRAPHS**

