

Sample No: VCP416034
Oil Type: VOLVO WB 102

Job No: SW1022432 BALCONES

SAMPLE	E INFORMATION	I		
Sample Number	<u> </u>	VCP416034	 	
Sample Date		21 Aug 2023	 	
Machine Hours		1436	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	42.0	 	
Visc @ 40 C	CSt	42.0		
VOLVO				
CONTAIN	MINATION			
Silicon	ppm	■28	 	
Sodium	ppm	4	 	
Potassium	ppm	■<1	 	
WEAR N	AETAL C			
WEAR	JE I ALS			
ron	ppm	■358	 	
Copper	ppm	■ <1	 	
Lead	ppm	■0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	■4	 	
Chromium	ppm	6	 	
Molybdenum	ppm	13	 	
Nickel	ppm	2	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	12	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	4063	 	
Magnesium	ppm	■18	 	
Zinc	ppm	1608	 	
Phosphorus	ppm	■1335	 	
Barium	ppm	■0	 	
Boron	ppm	144	 	
	PP.11			



ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO6174Unique No:10622854Signed:Wes DavisReport Date:30 Aug 2023



CONSTRUCTION EQUIPMENT





GRAPHS

