

Sample No: VCP420016

Oil Type: **DIESEL ENGINE OIL SAE 15W40**

Job No: **GOLF RENTAL**

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	•	VCP420016	 	
Sample Date		31 Aug 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		SEVERE	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	△ 6.9	 	
Base Number (BN)	mg KOH/g	■8.6	 	
Oxidation (PA)	%	67	 	
CONTAMI	NATION			
Soot %	%	■ 0.2	 	
Nitration (PA)	%	65	 	
Sulfation (PA)	%	53	 	
Glycol	%	NEG	 	
Fuel	%	38.4	 	
Silicon	ppm	□ 7	 	
Sodium	ppm	■3	 	
Potassium	ppm	■ <1	 	
VOLVO				
WEAR ME	TALS			
Iron	ppm	17	 	
Copper	ppm	■ <1	 	
Lead	ppm	■ 0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	1	 	
Chromium	ppm	■ <1	 	
Molybdenum	ppm	■29	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	■ <1	 	
Silver	ppm	■0	 	
Manganese	ppm	- <1	 	
Vanadium	ppm	0	 	
VOLVO	·			
ADDITIVE	.7			
Calcium	ppm	1160	 	
Magnesium	ppm	■385	 	
Zinc	ppm	792	 	
Phosphorus	ppm	649	 	
Barium	ppm	0	 	
Boron	ppm	■38	 	

ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: DEWAYNE BEARD DBeard@flaglerce.com T: (239)481-8554

F: (239)481-3302

Diagnosis

We advise that you check the fuel injection system. We recommend that you drain the oil and perform a filter service on this component if not already done. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a high amount of fuel present in the oil. Fuel is present in the oil and is lowering the viscosity. The oil is no longer serviceable due to the presence of contaminants.

Depot: VOLVO0090 **Unique No:** 10632423 Signed: Don Baldridge Report Date: 06 Sep 2023



CONSTRUCTION EQUIPMENT





GRAPHS

