Sample No: VCP407688

Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Job No: SWA341088

SAMPLE	INFORMATION				
Sample Number	-	VCP407688			
Sample Date		26 Aug 2023			
Machine Hours		16482			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	26.9			
Visc & 10 C	COL				
VOLVO					
LONTAM	IINATION				
Silicon	ppm	■4			
Sodium	ppm	■<1			
Potassium	ppm	■<1			
WEAR M	ETALS				
Iron	ppm	136			
Copper	ppm	10			
Lead	ppm	■0			
Tin	ppm	■0			
Aluminum	ppm	■0			
Chromium	ppm	■0			
Molybdenum	ppm	■ <1			
Nickel	ppm	■ 0			
Titanium	ppm	■0			
Silver	ppm	■0			
Manganese	ppm	■ <1			
Vanadium	ppm	0			
VOLVO					
ADDITIV	ES				
Calcium	ppm	103			
Magnesium	ppm	2			
Zinc	ppm	■18			
Phosphorus	ppm	192			
Barium	ppm	2			
Boron	ppm	■88			



MR BULTS INC

SULLIVAN COUNTY LANDFILL MONTICELLO, NY US 12701 Contact:

T: (208)324-7148 F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:MRBMONNYUnique No:10633295Signed:Wes DavisReport Date:06 Sep 2023

Contact/Location: ? ? - MRBMONNY



CONSTRUCTION EQUIPMENT





GRAPHS

