



CONSTRUCTION EQUIPMENT

SPM595559 KOMATSU D39 3729 - RIGHT FINAL DRIVE



Sample No: VCP413965
Oil Type: TDTO FLUID SAE 30
Job No: SPM595559



SAMPLE INFORMATION

Sample Number	VCP413965	---	---	---
Sample Date	28 Aug 2023	---	---	---
Machine Hours	1034	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ABNORMAL	---	---	---

JOHN KENO & CO
 750 RICARD LN
 ELK GROVE VILLAGE, IL
 US 60007
 Contact: LUKAS DECKER
 ldecker@johnkeno.com
 T: (847)340-2432
 F:



OIL CONDITION

Visc @ 40°C	cSt	■ 94.6	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 62	---	---	---
Sodium	ppm	■ 5	---	---	---
Potassium	ppm	■ 6	---	---	---

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. All other metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	■ 301	---	---	---
Copper	ppm	▲ 162	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 6	---	---	---
Chromium	ppm	■ 4	---	---	---
Molybdenum	ppm	■ 27	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	7	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 8	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	■ 3684	---	---	---
Magnesium	ppm	■ 14	---	---	---
Zinc	ppm	■ 805	---	---	---
Phosphorus	ppm	■ 719	---	---	---
Barium	ppm	■ 19	---	---	---
Boron	ppm	■ 4	---	---	---

Depot: JOHELK
Unique No: 10634531
Signed: Don Baldrige
Report Date: 08 Sep 2023



CONSTRUCTION EQUIPMENT



GRAPHS

