

CONSTRUCTION EQUIPMENT 3495BR VOLVO L180F 11639 - FRONT AXLE



Sample No: VCP415390

Oil Type: TDTO FLUID SAE 10W

Job No: 3495BR

SAMPLE	INFORMATION				
Sample Number	_	VCP415390			
Sample Date		05 Sep 2023			
Machine Hours		14979			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	46.6			
VISC @ 40 C	CSt	40.0			
VOLVO					
CONTAM	IINATION				
Silicon	ppm	1 9			
Sodium	ppm	■3			
Potassium	ppm	0			
WEAR METALS					
Iron	ppm	■87			
Copper	ppm	■0			
Lead	ppm	0			
Tin	ppm	0			
Aluminum	ppm	7			
Chromium	ppm	■<1			
Molybdenum	ppm	■0			
Nickel	ppm	0			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm				
Vanadium	ppm	0			
VOLVO					
ADDITIV	ES				
Calcium	ppm	1936			
Magnesium	ppm	21			
Zinc	ppm	954			
Phosphorus	ppm	768			
Barium	ppm	0			
Boron	ppm	63			



HIGHWAY EQUIPMENT AND SUPPLY CO 200 BURKHOLDER DR. EPHRATA, PA US 17522 Contact: CHAD HERRON chad@hwyequip.com T: (717)859-3132

Diagnosis

F: (717)859-2698

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) TDTO FLUID SAE 10W. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:INSEPHUnique No:10635546Signed:Wes DavisReport Date:08 Sep 2023



CONSTRUCTION EQUIPMENT





