

## CONSTRUCTION EQUIPMENT 23898 VOLVO L60H 622169 - FRONT AXLE



Sample No: VCP424651

Oil Type: VOLVO WB 102

**Job No:** 23898

ZAMPLE	E INFORMATIO	N		
		VCP424651	 	
Sample Number				
Sample Date		06 Sep 2023	 	
Machine Hours		1954	 	
Oil Hours		2000	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>41.4</b>	 	
VOLVO	MINATION			
	MINATION			
Silicon	ppm	<b>1</b> 3	 	
Sodium	ppm	<b>10</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR N	METALS			
Iron	ppm	<u></u> 47	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	<b>=</b> <1	 	
Tin	ppm	<b>-</b> <1	 	
Aluminum	ppm	<b>0</b>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	<b>2</b>	 	
Nickel	ppm	<b>0</b>	 	
Titanium		0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>3</b>	 	
Vanadium	ppm	0	 	
variaululli	ppm	U	 	
VOLVO				
ADDITIV	VES			
Calcium	ppm	<b>4325</b>	 	
Magnesium	ppm	<b>■30</b>	 	
Zinc	ppm	■1734	 	
Phosphorus	ppm	■1371	 	
Barium	ppm	■0	 	
Boron	ppm	<b>146</b>	 	



218 - ASCENDUM MACHINERY INC - N. CHARLESTON 7235 CROSS COUNTRY RD. NORTH CHARLESTON, SC US 29418 Contact: MATT MITCHAM matt.mitcham@ascendummachinery.com T:

F: (843)414-1129

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3387Unique No:10646489Signed:Wes DavisReport Date:15 Sep 2023



## **CONSTRUCTION EQUIPMENT**





